TEST REPORT

No. : SZIN1811014835PS
Date : Nov 14, 2018

CUSTOMER NAME:
ADDRESS:

CANOPIA
Protégez vos yeux

Sample Name	:	ACRYLIC ANTI-BLUE RAY FILM
Product Specification	:	21 INCH
Manufacturer	:	
Material and Mark	:	ACRYLIC

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

SGS Ref. No.	:	GZIN1811058335MR
Date of Receipt	:	Nov 07, 2018
Testing Start Date	:	Nov 07, 2018
Testing End Date	:	Nov 14, 2018
Test result(s)	:	For further details, please refer to the following page(s) (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Services Co., Ltd. Shenzhen Branch
Testing Center

James Zheng

James Zheng
Authorized signatory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center- Materials Laboratory
检验检测专用章 Inspection & Testing Services
SGS Bldg, No. 4 ,Jianghao Industrial Park, No. 430 ,Jihua Road, Bantian , Longgang District , Shenzhen, China 518129 t (86–755) 25328282 f (86–755) 83197625 www.sgsgroup.com.cn
中国・深圳・龙岗区坂田吉华路430号江灏工业园4栋SGS大楼 邮编: 518129 t (86–755) 25328282 f (86–755) 83197625 e sgs.china@sgs.com
Member of the SGS Group (SGS SA)

TEST REPORT

No. : SZIN1811014835PS

Date : Nov 14, 2018

Summary of Results:

No.	Test Item	Test Method	Result
1	Transmittance	With reference to ASTM E903-12 and client's requirement	55.1%

Original Sample Photo:



Sample A

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center- Materials Laboratory.

SGS Bldg, No. 4 ,Jianghao Industrial Park, No. 430 ,Jihua Road, Bantian , Longgang District , Shenzhen, China 518129 t (86-755) 25328282 f (86-755) 83197625 www.sgsgroup.com.cn

中国 • 深圳 • 龙岗区坂田吉华路430号江灏工业园4栋SGS大楼 邮编: 518129 t (86-755) 25328282 f (86-755) 83197625 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : SZIN1811014835PS

Date : Nov 14, 2018

Test Item: Transmittance

Sample Description: See photo

Test Method: With reference to ASTM E903-12 and client's requirement

Test Condition:

Specimen thickness: 2.01mm

Test model: Transmittance

Wavelength range: 420nm ~460nm

Wavelength interval: 5nm

Scan speed: Middle

Lab Environmental Condition: (23±2)℃, (50±5)%RH

Test Result:

Test Item	Test Result
Transmittance	55.1%

Original data:

Wavelength, nm	Transmittance, %
460	59.8
455	59.3
450	58.9
445	58.4
440	57.8
435	56.8
430	55.0
425	50.9
420	38.7

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center- Materials Laboratory

SGS Bldg, No. 4 ,Jianghao Industrial Park, No. 430 ,Jihua Road, Bantian , Longgang District , Shenzhen, China 518129 t (86–755) 25328282 f (86–755) 83197625 www.sgsgroup.com.cn

中国 • 深圳 • 龙岗区坂田吉华路430号江灏工业园4栋SGS大楼 邮编: 518129 t (86–755) 25328282 f (86–755) 83197625 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

Note:

1. Test specimens were cut from the sample.
2. The protected film of test specimens was ripped off before test.
3. The above test was carried out by SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

Cuvre:



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com
SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center- Materials Laboratory.
SGS Bldg, No. 4 ,Jianghao Industrial Park, No. 430 ,Jihua Road, Bantian , Longgang District , Shenzhen, China 518129 t (86-755) 25328282 f (86-755) 83197625 www.sgsgroup.com.cn
中国·深圳·龙岗区坂田吉华路430号江灏工业园4栋SGS大楼 邮编: 518129 t (86-755) 25328282 f (86-755) 83197625 e sgs.china@sgs.com
Member of the SGS Group (SGS SA)

TEST REPORT

Test Photo:

	
During test	Before test

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Ultra-violet Spectrophotometer	TU-1810DASPC	GZMR-PL-E225	2018-07-17	2019-07-16

******** End of report********

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center- Materials Laboratory.
SGS Bldg, No. 4 ,Jianghao Industrial Park, No. 430 ,Jihua Road, Bantian , Longgang District , Shenzhen, China 518129 t (86–755) 25328282 f (86–755) 83197625 www.sgsgroup.com.cn
中国 • 深圳 • 龙岗区坂田吉华路430号江灏工业园4栋SGS大楼 邮编: 518129 t (86–755) 25328282 f (86–755) 83197625 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)